

- 789.** Sastry, G. and Bhatt, P.N. 1980. Performance of gully control structures in outer Himalayas of Doon Valley. *Indian J. Soil Conserv.*, 8(2):130-139.

The reasons for mal-functioning of gully control structures have been investigated and reported. It is found that main cause of failure of these structures is the non-provision of basic components such as spillway, head wall extension, apron, etc. in addition to improper selection of site. Hydrologic and hydrolic design details have been presented briefly in the paper for the structures under study.